

| | | | |
|-------|------------|--------|-------------|
| No: | SB140-13 | Issue: | 001 |
| Date: | 22/03/2013 | Sheet: | Page 1 of 1 |

SUBJECT: Volvo Engine E5, Re-position Wiring Loom.

It has been reported that some vehicles have been delivered with a wiring loom incorrectly installed making it possible for the loom to be in contact with the air inlet pipe.



On your next vehicle inspection please check the routing of the loom, and re position if necessary as shown below. Check the air inlet pipe and replace if any damage is present.

