

No:	SB153-16	Issue:	1
Date:	14/01/16	Sheet:	Page 1 of 2

SUBJECT: Elite 6 Lower Rocker Cover Gasket Leakage – Volvo Campaign S3454

Certain Volvo D8 K engines have a **lower rocker cover gasket** that could potentially leak, this could lead to the low engine oil level warning showing on the Instrument Cluster.

Dennis Eagle Warranty have a list of affected vehicles and will be contacting those customers directly but it is still best to check your vehicle in case there is a clerical error within the Volvo database.

To identify if you have a potential faulty gasket you need to look at the manufactures tag to see which country the gasket is manufactured in.

Fig 1. below shows the position of the manufacturers tag.

Fig 1. Position of tag



To check the **lower gasket tag** remove the sensor plug and pull the sensor loom away from the engine in the tag area (shown in Fig 2. on page 2), if your tag is marked **India** no further action is required.

If the tag is marked **Portugal** there is a potential for the gasket to leak, in experience this usually happens within the first 1000 miles of engine use. All gaskets marked Portugal regardless of mileage should be changed by your local Volvo dealer quoting **S3454** as a reference, the cut-off date for the rework is 30/04/2017.

No:	SB153-16	Issue:	1
Date:	14/01/16	Sheet:	Page 2 of 2

SUBJECT: Elite 6 Lower Rocker Cover Gasket Leakage – Volvo Campaign S3454

Fig 2.

Shows a lower tag marked *India*; no further action required.

