

No:	SB163-16	Issue:	1
Date:	10/10/2016	Sheet:	Page 1 of 1

SUBJECT: EBS Warning Lamps on Elite 6 Vehicles

There have been some concerns raised regarding the EBS warning lamp operation on Elite 6 vehicles when being presented for their annual test.

There are two warnings that appear when the ignition is switched on; one is a pictogram below the Dennis Eagle logo on the instrument cluster (Fig.1 or Fig.2), the other is a lamp on the bottom of the instrument cluster (fig.3). Both will extinguish after a system check providing there is no system malfunction.

Fig.1



Fig.2



Fig.3

