

No: SB168-17

Date: 23/05/17

Issue:

1

Subject: Olympus Rear Body Chute Security (Optional Extra)

Dennis Eagle have received a small number of reports of the rear body chutes mounted on the Olympus bodies coming loose due to the nut inserts pulling through the rear body cross member.

As a precautionary measure Dennis Eagle need customers to inspect and check the security of the chute and include this check on all future six weekly inspections. If you find your chute has come loose please remove it from the body and report it to your local service centre along with vehicle identification details. Dennis Eagle will then make arrangements to come and refit the chute.



Olympus body rear chute



8 x fixings into rear cross member